

Gefahrhinweis FR

Interner Verweis: SOFRTE-29PF

Previous requirements for H.V. ELECTRICAL INSTALLATION works

DANGER 

BEFORE STARTING ANY WORK IN HIGH VOLTAGE INSTALLATIONS:

- 1** **CUT** ALL POSSIBLE HIGH AND LOW VOLTAGE SUPPLY WHERE IT HAS TO BE OPERATED, USING, AT LEAST, HELMET, INSULATING STOOL, DIELECTRIC GLOVES AND PROTECTIVE GLASSES.
- 2** WHEN **USING** POLES, CLEAN THEM AND CONNECT IT TO EARTH IF NEEDED.
- 3** **BLOCK** THE CUTTING DEVICES, WHEN IT IS POSSIBLE.
- 4** **PLACE ON** THE CUTTING DEVICES CONTROL THE APPROPRIATE SAFETY SIGN.
- 5** **ALWAYS CHECK** VOLTAGE ABSENCE OF THE ELEMENTS WHERE WE NEED TO WORK OR THE ONES PLACED IN A DISTANCE THAT INVOLVES DANGER.
- 6** **PLACE** THE EARTHING AND SHORT CIRCUIT EQUIPMENTS IN ORDER TO INSULATE THE AREA.

IT IS TOTALLY FORBIDDEN TO GO INTO THE CELL BEFORE ENSURING THERE IS NO VOLTAGE PRESENCE INSIDE.

0

Characteristics

Dimension

210x297 mm